

# Vehicle Inspection Grading



- Mileage not over 20,000 kilometers
- Vehicle registration not over 1 year (Not manufacturing year)
- No paint repair, body part replace, removable scratches
- Interior in good condition



- Mileage not over 50,000 kilometer
- Vehicle registration 1-3 years (Not manufacturing year)
- Minor scratches, stone flakes, dent, Scuffed not reach metal
- Paint repairs



- Mileage not over 120,000 kilometer
- Vehicle registration 3-5 years (Not manufacturing year)
- Scratches, stone flakes, dent, scuffed not reach metal
- Paint repairs, body parts removed for repair, bolted body parts replaced



- Absorption beam repaired or replaced
- Body parts removed/repaired/replaced
- Crash from front-back but did not hit main structure
- Scratches, stone flakes, dent, scuffed deep to metal
- Moderate repairs around the body
- Rust under seats/console but can not detect flooding/carpet level
- LPG/CNG installed
- Engine transplanted, color changed



- Major accident damage to vehicle structure
- Wheel well damage, damage to shock absorber mount
- Damage to vehicle spot weldings/arches
- Chassis damaged/repaired, chassis/car floor rust to decay
- Roof damage
- Chassis cutted/edited/rust to decay, chassis & engine number tampered, vehicle repaired from accident, expand intercooler
- No plate, plate tampered (Except paper plate)
- Spare tire compartment repaired, Pick up chassis repaired
- Flooded



- Cannot drive, engine/gear malfunction, hybrid system issue



- Salvage condition